

TO BE FILLED BY THE INSPECTING OFFICER (ASSISTANT ENGINEER)


NIKHIL ROY

- | | | |
|-----|---|---|
| 1 | Name of the Office | Thripatha English Medium School |
| 2 | Name of School | Thripatha, Palakkad |
| 3 | Location/with name of Education
Dist / Sub Dist | Thripatha, Palakkad |
| 4 | Classification of building and size | 1- 6.00 x 6.00 x 3.60 - 10 Nos - Tiled Roof
2- 6.16m x 6.25 x 3.60m - 2 Nos - RCC |
| 5 | Period for which the certificate is issued | 2022-24
3. 5.55m x 7.42m x 3.60m - 2 Nos - RCC
4. 6.92m x 7.42m x 3.60m - 2 Nos - RCC
5. 6.16m x 6.25m x 3.60m - 2 Nos - RCC
6. 6.00m x 6.00m x 3.60m - 10 Nos - RCC
7. 6.00m x 6.00m x 3.60m - 1 nos - GI sheet |
| 6 | Nature of defect if any | } Nil |
| (a) | Foundation and Basement | |
| (b) | Superstructure | |
| (c) | Doors and Windows | |
| (d) | Wood Work Wrought put up | |
| (e) | Roof | |
| (f) | Flooring | |
| (g) | Miscellaneous cracks etc | |
| 7 | Any major defects noticed which will render the building unsafe if any manner | |
| 8. | Whether the maintenance works have been done properly | Yes, found for condenser clean under normal wind, heavy and other |
| 9. | Whether the structure is sound or not for conducting classes. | Yes. Upto condition. |

- Notes:
1. The stability of the structure should be examined also with reference to location attitude intensity of wind exposure to flood, etc.
 2. Any additional observations is seemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 22/01/2023 / 31/05/2023 and found to be fit / unit to conduct classes for the period 2022-24 for the reason stated above

Place : Thripatha
Date : 21/05/2023



(Signature)
PRESIDENT
Thripatha English Medium
Senior Secondary School
P. O. Thripatha

(Signature)
PRINCIPAL
TRIPATHA ENGLISH MEDIUM SCHOOL